Smart Contact Point cant Capture Contact Point Precisely

Troubleshooting · https://dropletlab.com/knowledge-doc/what-to-do-if-smart-contact-points-cannot-capture-the-contact-points-precisely/

In such cases, it is recommended to deposit the drop as possible to the camera as the maximum focus allows which is the maximum value of the focus slider. Alternately it is an error with the image calibration number; measure the needle thickness and try the calibration process again.